

Date and Time	User	Group	Action and Reason
2022-04-06 10:25:37	TnJ	OEM	Run Started
2022-04-19 23:17:30	admin	Admin	testing comment at data management windows Added at: 2022-04-20 23:17:36
2022-04-20 09:34:55	TnJ	OEM	Set Agit_Status (Agit_Bool) to TRUE
2022-04-20 09:35:36	TnJ	OEM	Acid flow SP changed to 1 from 0
2022-04-20 09:35:36	TnJ	OEM	AF Flow SP changed to 2 from 0
2022-04-20 09:35:36	TnJ	OEM	Agit SP changed to 400 from 0
2022-04-20 09:36:06	TnJ	OEM	Acid flow SP changed to 2 from 1; Reason: per SOP
2022-04-20 09:36:06	TnJ	OEM	AF Flow SP changed to 3 from 2; Reason: per SOP
2022-04-20 09:37:49	TnJ	OEM	Feed1 Flow SP changed to 50 from 0; Reason: per sop
2022-04-20 09:37:49	TnJ	OEM	Feed2 Flow SP changed to 30 from 0; Reason: per sop
2022-04-20 10:24:28	admin	Admin	Set pH Controller by Acid to Auto; Reason: per SOP
2022-04-20 10:24:28	admin	Admin	Set DO Controller to Auto; Reason: per SOP
2022-04-20 10:24:50	admin	Admin	Set R1 Feed6 to run mode; Reason: SOP
2022-04-20 18:16:33	admin	Admin	Acid flow SP changed to 1 from 0; Reason: per sop Success!
2022-04-20 18:16:33	admin	Admin	AF Flow SP changed to 1 from 0; Reason: per sop Success!
2022-04-20 18:16:33	admin	Admin	Agit SP changed to 100 from 0; Reason: per sop Success!
2022-04-20 18:16:33	admin	Admin	Air_1 Flow SP changed to 1 from 0; Reason: per sop Success!
2022-04-20 18:16:33	admin	Admin	Base flow SP changed to 1 from 0; Reason: per sop Success!
2022-04-20 18:16:33	admin	Admin	DO_SP changed to 40 from 0; Reason: per sop Success!
2022-04-20 18:16:33	admin	Admin	Feed1 Flow SP changed to 1 from 0; Reason: per sop Success!
2022-04-20 18:40:28	admin	Admin	Set Temper Control by Cooling to Auto from Manual; Reason: testing, successful Modified: 2022-04-20 22:28:46
2022-04-20 18:40:28	admin	Admin	Set Temper Control by Heating to Auto from Manual; Reason: testingNot Found
2022-04-20 18:40:28	admin	Admin	Set pH Controller by Base to Auto from Manual; Reason: testingNot Found
2022-04-20 18:44:55	admin	Admin	Set Temper Control by Cooling to Manual from Auto; Reason: testing; Not Found
2022-04-20 18:47:09	admin	Admin	Set DO Controller to Auto from Manual; Reason: testing; Successful
2022-04-20 18:47:09	admin	Admin	Set Temper Control by Heating to Auto from Manual; Reason: testing; Successful
2022-04-20 23:17:00	admin	Admin	test commenting at main window
2022-04-24 15:06:00	admin	Admin	Changed Agit_SP from 0 to 500; Reason: SP change on HMI
2022-04-24 15:06:00	admin	Admin	Set Agit_Status (Agit_Bool) to TRUE; Reason: Start Agitation
2022-04-24 15:12:00	admin	Admin	Changed Agit_SP from 500 to 600; Reason: DO is low
2022-04-24 15:12:00	admin	Admin	Changed DO_SP from 0 to 40; Reason: per SOP

Date and Time	User	Group	Action and Reason
2022-04-24 15:14:00	admin	Admin	pH_SP changed to 5.5 from 0; Reason: per SOP; Successful.
2022-04-24 15:14:00	admin	Admin	Temperature_SP changed to 36.8 from 0; Reason: per SOP; Successful.

---

Date and Time	User	Group	Sample	Parameter	Old	New	Reason of change
2022-04-06 12:54:40	TnJ	OEM	15	Residual Glucose	0	1.234	Not Provided